


AUDITOR'S CERTIFICATE

1 of 1 3:10PM

ASSOCIATES

DEPUTY



LEGEND

- | | |
|-------|--|
| SP | SET 1/2" REBAR WITH #14A 27327. CAP |
| PROS | FOUND IRON PIPE AS NOTED |
| | FOUND REBAR AS NOTED |
| | FOUND PLAT MONUMENT AS NOTED |
| (P) | RECORD PLAT DISTANCE |
| (P*) | ERRONEOUS PLAT DISTANCE SEE NOTE 8 |
| (M) | MEASURED DISTANCE |
| | CALCULATED DISTANCE |
| ADJAN | REFERENCE TO SKAGIT COUNTY AUDITOR'S FILE NUMBER |
| | REFERENCE TO SKAGIT COUNTY RECORD OF SURVEY |
| | REFERENCE TO SKAGIT COUNTY SHORT PLAT |

NOTES

1. BASIS OF BEARINGS: S 69° 24' 00" E ALONG THE CENTERLINE OF NORTH SHORE DRIVE, AS MONUMENTED AND SHOWN HEREON, AND BY THE PLAT OF LAKE CAVANAUGH SUBDIVISION, DIVISION NO. 1, AS RECORDED IN VOLUME 5 OF PLATS, PAGES 37 TO 43, RECORDS OF SKAGIT COUNTY, WASHINGTON.
2. THIS SURVEY WAS ACCOMPLISHED BY FIELD TRAVERSE WITH A 3 SECOND ELECTRONIC DIGITAL TOTAL STATION.
3. THIS SURVEY MEETS OR EXCEEDS THE ACCURACY STANDARDS SPECIFIED BY WAC 332-130-080.
4. THE LEGAL DESCRIPTION RECITED HEREON IS FROM THAT OUTCAME DEED RECORDED UNDER SKAGIT COUNTY AUDITORS FILE NO. 9890160092.
5. THIS SURVEY DOES NOT PURPORT TO SHOW ALL EASEMENTS OR ENCUMBRANCES, RECORDED OR UNRECORDED, THAT MAY AFFECT THE DEPICTED PROPERTIES.
6. ENCUMBRANCES ARE DEPICTED HEREON IN ACCORDANCE WITH THE REQUIREMENTS OF WAC 332-130-060. THIS SURVEY DOES NOT RESOLVE ISSUES OF ENCUMBRANCEMENT OR OCCUPATION.
7. A SURVEY OF PARCELS A AND B IS RECORDED UNDER SKAGIT COUNTY AUDITORS FILE NO. 201307260110.
8. THE DISTANCES ALONG THE NORTH LINES OF LOTS 21 THROUGH 24, BLOCK 1, LAKE CAVANAUGH SUBDIVISION, DIVISION NO. 1, ARE ARITHMETICALLY REPORTED ON SHEET 3 OF THE PLAT. THIS WAS THE RESULT OF DISTRIBUTING THE TOTAL DISTANCE FROM THE INTERSECTION OF THE SOUTHERLY MARSHES OF BALBOA LAKE AND NORTH SHORE DRIVE, AT THE CORNER OF LOTS 20 AND 21, TO THE POINT OF CURVATURE IN THE SOUTH MARSH OF NORTH SHORE DRIVE ON THE NORTHEASTLY LINE OF LOT 25, BEFORE SUBTRACTING THE DISTANCE OF 6.14 FEET, WHICH IS PART OF LOT 25 ROAD FRONTAGE. CORRECTED DISTRIBUTION OF DISTANCES ALONG THE NORTH LINES OF THESE LOTS AS DEPICTED HEREON PRODUCES A MATHEMATICAL CLOSURE OF 0.10 FEET FOR THE EXTENSION BOUNDARY OF LOTS 21 THROUGH 24.

LEGAL DESCRIPTION

LOT 23, BLOCK 1, LAKE CAVANAUGH SUBDIVISION, DIVISION NO. 1, ACCORDING TO THE PLAT RECORDED IN VOLUME 5 OF PLATS, PAGE 37 TO 43 INCLUSIVE, RECORDS OF SRAIGT COUNTY WASHINGTON.

TOGETHER WITH EASEMENT AGREEMENT NO. 893908, FILED IN SKAGIT COUNTY ON DECEMBER 29 1978.

SITUATE IN THE COUNTY OF SKAGIT, STATE OF WASHINGTON

MOMSEN LIVING TRUST

RECORD OF SURVEY


SCALE: 1" = 40'		SHEET 1 OF 1
DRAWN BY: JBS SEPT. 26, 2013		DWG: MOMMSSEN
REVISED:	603 SOUTH FIRST STREET MOUNT VERNON, WA 98275 TEL: (360) 336-9199	
F/B: MW99 PG 14 09B-13-107	S.T.R. INDEX S22-123N-ROE GOVT LOT 2	

THIS MAP CORRECTLY REPRESENTS A SURVEY MADE BY ME OR UNDER MY
DIRECTION IN CONFORMANCE WITH THE REQUIREMENTS OF THE SURVEY
RECORDING ACT AT THE REQUEST OF DANIEL G. FIDEMORE IN JUNE, 2013.

James B. Smith

JAMES B. SMITH, PLS, CREDS

UNPUBLISHED WORK © 2013



El/ai/al

SECTION 22 T2N 33N R3E 05E WM

LAKE CAVANAUGH

60.00 120.00 60.00 60.00 19.70

S 87°18'00" E 919.7 (P)

22

7 8 9 10 11

SURVEYOR'S CE

THIS MAP CORRECTLY REPRESENTS
DIRECTION IN CONFORMANCE WITH
RECORDING ACT AT THE REQUEST

James B. Smith
JAMES B. SMITH, PLS., CHES

FOUND POINT DESCRIPTIONS

- ① FOUND 2/5/6 REBAR WITH NO CAP EXPOSED 1.103 E 4.51 OF CALCULATED LOCATION
② FOUND 2/5/6 DIAMETER OPEN IRON PIPE S 0.625 S 3.46 OF CALCULATED LOCATION
③ FOUND 1/1/4" OUTSIDE DIAMETER PUNCHED IRON PIPE S 1.06 E 1.16 OF CALCULATED LOCATION
④ FOUND 1/1/4" OUTSIDE DIAMETER PUNCHED IRON PIPE S 3.66 E 7.28 OF CALCULATED LOCATION
⑤ FOUND 2/ OUTSIDE DIAMETER OPEN IRON PIPE WITH REBAR EXPOSED INSIDE S 3.95 E 7.34 OF CALCULATED LOCATION
⑥ FOUND 1/1/4" OUTSIDE DIAMETER PUNCHED IRON PIPE DOWN 1.5 S 1.27 E 8.99 OF CALCULATED LOCATION
⑦ FOUND 1/1/4" OUTSIDE DIAMETER PUNCHED IRON PIPE S 0.17 W 0.03 OF CALCULATED LOCATION
⑧ FOUND 3/4" OUTSIDE DIAMETER OPEN IRON PIPE S 0.96 W 0.22 OF CALCULATED LOCATION
⑨ FOUND 1" OUTSIDE DIAMETER OPEN IRON PIPE EXPOSED 3.1 N 0.6 E 9.77 OF CALCULATED LOCATION
⑩ FOUND 1/1/4" OUTSIDE DIAMETER PUNCHED IRON PIPE (APPEARS DISPLACED) S 0.10 W 0.20 OF CALCULATED LOCATION
⑪ FOUND 5/6 REBAR WITH NO CAP EXPOSED 1.5 S 0.49 W 0.22 OF CALCULATED LOCATION
⑫ FOUND 5/6 REBAR WITH NO CAP EXPOSED 1.0 S 1.00 W 0.22 OF CALCULATED LOCATION
⑬ FOUND 1/1/4" REBAR WITH NO CAP EXPOSED 0.4 N 0.03 E 0.28 OF CALCULATED LOCATION
⑭ FOUND 1/2" REBAR WITH NO CAP EXPOSED 2. W 0.73 OF PROJECTED LINE OF PARCEL A AND LOT 22
⑮ FOUND 1/2" REBAR WITH NO CAP EXPOSED 1. E 1.27 OF PROJECTED LINE OF PARCEL B AND LOT 23

SECTION INDEX

SECTION 22 TYN 33N RGE 6E MM
JLIMBO\HARMSEN\WORK\PROJECTS\2013\13-10Z PUGERUDE\13-10Z ROS AC2009.DWG

UNPUBLISHED WORK © 2013 BY HARMSSEN & ASSOCIATES INC.